

**KIT DE RÉPARATION / MAINTENANCE DE SOUPAPE**  
**REPAIR KIT**



**CARACTÉRISTIQUES / SPECIFICATIONS**

Le modèle **EU-SP-VRKMK81A** est un kit de réparation / maintenance pour le modèle EU-SP-MK81A spécial soupape antigel.

**EU-SP-VRKMK81A** is a repair kit for model EU-SP-MK81A.

**PRODUITS COMPATIBLES /  
COMPATIBLE PRODUCTS**

EU-8327FP  
EU-8327FP-AXION  
EU-8327FPCR  
EU-8327FPCR-AXION  
EU-8400FP  
EU-8400FP-AXION  
EU-SP-MK81A

### ATTENTION INSTALLER :

Please compare the brass spools.

If the top o-ring groove of the new spool is roughly 1/16" lower than the top o-ring groove of the old spool, use your old spool, but replace the o-rings and the seat washer with the new parts from the new spool. If your old spool matches the new spool, replace the complete assembly.

### INSTALLATION INSTRUCTIONS :

1. Shut off water supply.
2. Disconnect linkage assembly from top of old stem assembly.
3. Remove stuffing box.
4. Remove old stem end sub-assembly.
5. Examine seat area of underground valve body for damage or debris.
6. Turn on water and flush if debris found.
7. Replace stem end sub-assembly.
8. Reinstall stem end sub-assembly with new spring, stuffing box, felt T ring and packing nut.
9. Reconnect linkage assembly.
10. Turn on water supply.
11. Test unit.

## STEM END SUB-ASSEMBLY

